
Clifton MGP OU2 Site Remediation Public Availability Session Slides and Materials


M.L. Lindenmeyer-High School December, 2011


Station 1: Health Issues and Questions

Perimeter Air Monitoring



Previous OU-1 CAMP Data






Station 2: Site Construction and Schedule


Site Prep/Site Layout




Slurry Wall & Excavation Location



Excavation and Tent Layout




Schedule



Station 3: Environmental Controls

Excavation Approach



Fabric Structure











Noise Monitoring Locations



Vibration Monitoring Locations



S1 RECEPTOR LOCATION

SETTLEMENT
MONITORING LOCATION





NATIONAL GRID FORMER MANUFACTURED GAS PLANT 60137363-430

PROPOSED VIBRATION AND SETTLEMENT MONITORING LOCATIONS

DATE: 06/2011

FIGURE 2-1

Treated Water Monitoring Locations

APPROXIMATE LOCATION OF CONSTRUCTION WATER MONITORING STATION





DATE: 12/2011


FIGURE 1


Station 4: Traffic and Site Controls

Sidewalk Closures and Parking




Trucking Routes





Disposal Locations



Trucking Approach







