

NEW YORK STATE DEPARTMENT OF ENVIRONMENTAL CONSERVATION

Division of Environmental Remediation, Remedial Bureau C
625 Broadway, 11th Floor, Albany, NY 12233-7014
P: (518) 402-9662 | F: (518) 402-9679
www.dec.ny.gov

December 8, 2016

Katherine Vater, Project Manager
National Grid
Fleet Services Building/Administration Office
287 Maspeth Avenue
Brooklyn New York 11211


RE: 2016 First Semiannual Monitoring (SA1) Report
received November 14, 2016
Former Clifton MGP Site
Site No. 243023
Town of Clifton, Richmond County

Dear Ms. Vater:

The New York State Department of Environmental Conservation (the Department) has reviewed the 2016 First Semiannual Monitoring (SA1) Report for the Clifton MGP site, received November 14, 2016. The Report is hereby approved.

If you have any questions concerning this matter, please contact me at 518-402-9680.

Sincerely,



Richard H. Dana, CPG
Engineering Geologist
MGP Remediation Section

ec: Gardiner Cross
Stephanie Selmer, NYSDOH
Shail Pandya, AECOM
Andrew Prophete, National Grid



Department of
Environmental
Conservation